

 (B0B392) A x2	 (B392SE1P0) B x2	 (B392SE2BL) C x2	 (B392SE3BL) D x4	 (B392SE5BL) E x1	
 Ø 20 lg 1670 (B392SE4BL) F x1	 (PRB3904ZN) G x1	 M6 x 50 (VIH06 50 88) H x8	 M6 x 80 (VIH06 80 88P) I x4	 M6 (VEH06NY) J x14	
 (EMC40I) K x12	 (VRM06) L x14	 55mm (VIAR05 55) M x12	 150 1820 (B0B3911) N x2	 900 1820 (B0B3912) O x2	
 (B391SE1BL) P x1	 (B391SE2BL) Q x2	 (B391SE3BL) R x2	 Ø 25 lg 1610 (B391SE4BL) S x1	 (PRB3911ZN) T x2	
 M6 x 90 (VIH06 90 88P) U x4	 (PRB3912) V x2	 (EM25I) W x6	 40mm (VIAR05 40) X x6	 16mm (VIAR04 16) Y x8	 (B297ALSE) Z x6

SAV

Si malgré toutes les précautions prises lors de la conception du produit, vous deviez rencontrer un problème, notre Service Après Vente reste à votre disposition. Du lundi au jeudi : de 8h00 à 17h00 et le vendredi de 8h00 à 15h00



33 (0)3 20 10 90 25




33 (0)3 20 10 37 89



be-sav@mottez.com

1



2

